

Type in at BASIC prompt, press ENTER after every line and RUN when you are done. Twist head alignment screw carefully and slowly to achieve the least warped vertical lines of circles. If a number appears instead of **PRESS PLAY ON TAPE**, you mistyped some numbers.

```
0 DATA 32,23,248,120,169,23,133,1
1 DATA 32,252,230,169,4,133,212,169
2 DATA 139,141,17,208,173,17,208,16
3 DATA 251,162,30,160,0,169,16,200
4 DATA 44,13,220,240,250,173,32,208
5 DATA 73,14,141,32,208,152,74,168
6 DATA 202,224,2,176,230,169,81,145
7 DATA 211,224,0,208,222,142,33,208
8 DATA 165,211,212,165,212,201,8,208
9 DATA 2,230,169,155,141,17,208,32
10 DATA 190,169,166
11 DATA 179,238,202,208,250,32,68,229
12 DATA 80,10,97:READ B:POKE 256+A,B
13 FOR A=0 TO 13420 THEN SYS 256
14 C=C+B:NEXT IF C=13420 THEN SYS 256
15 PRINT C:REM MICRO ALIGN 0.1/ENTHUSI
```